

LRQA

LRQA

LRQA

Page 1 of 2

Certificate of Approval

This is to certify that the Management System of:

Antiwear (Suzhou) Industrial Intelligent Technology Co., Ltd.

No. 988, Yuexiu Road, Fenhu Economic Development Zone, Suzhou City, Jiangsu Province, China

Unified Social Credit Code: 913205096829757874

Registration Address: No. 988, Yuexiu Road, Fenhu Economic Development Zone, Suzhou City, Jiangsu

Province, China

LRQ

has been approved by LRQA to the following standards:

ISO 9001:2015 GB/T 19001-2016

Approval number(s): ISO 9001 - 0071334

This certificate is valid only in association with the certificate schedule bearing the same number on which the locations applicable to this approval are listed.

The scope of this approval is applicable to:

Design, manufacture and repairing service for disc valves, ball valve (including oxygen ball valve, lined ball valve and PDS ball valve), butterfly valve, gate valve, globe valve and check valve.



Davis Guan

Regional Director

LRQA Shanghai Office

Issued by: LRQA Limited



The certificate can be checked for validity on CNCA website (www.cnca.gov.cn) 30 working days after the date of issuance. Certified organization must accept periodical surveillance audit and certificate is continual valid after passing the audit

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



Certificate identity number: 10652477

Certificate Schedule

Location Activities

Antiwear (Suzhou) Industrial Intelligent Technology Co., I td.

No. 988, Yuexiu Road, Fenhu Economic Development Zone, Suzhou City, Jiangsu Province, China

ISO 9001:2015

Design, manufacture and repairing service for disc valves, ball valve (including oxygen ball valve, lined ball valve and PDS ball valve), butterfly valve, gate valve, globe valve and check valve.

Antiwear (Changshu) Fluid Control Technology Co., Ltd.

No. 18, Yunfan Road, Bixi Street, Changshu City, Jiangsu Province, China

ISO 9001:2015

Design, manufacture and repairing service for disc valves, ball valve (including oxygen ball valve, lined ball valve and PDS ball valve), butterfly valve, gate valve, globe valve and check valve.

UKAS MANAGEMENT SYSTEMS

0001

The certificate can be checked for validity on CNCA website (www.cnca.gov.cn) 30 working days after the date of issuance. Certified organization must accept periodical surveillance audit and certificate is continual valid after passing the audit.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 2 of 2

1004

LRQA

LPO

LRQA

LRQ/

LRQ/

LRQA

LRQ/

LRQ/

LPO/

LRQ/

LRQ/\

LIKC

LRQ/

LRQA